

Fan Shaft © (F. Pit)

© New Winning Winding Shaft

Extent of
Yard
Seam Workings from F. Pit

Probable Extent of Yard Seam

13' fault

Seam Workings

Boiler

Reservoir

from F. Pit

Bull St

Darby St

Railway St

Brooks St

Pit Railways

Surface Fractures

Scale - 2 Chains to an Inch.

16/7/07

© B. Pit